

- ✓ : Compatible
- ? : To be checked
- X : Not compatible

Last update: 08.01.2014

		3-wire kit	Spyder LM	Cobra AC	profilo LM AC	profilo WL AC	profilo harness AC	profilo RCU AC	Serenity DPC AC	primero DPC AC
<b>TETRA / TETRAPOL RADIO</b>										
115-1177	Motorola MTP 700 MTP 750	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1179	Motorola TCR 1000	X	X	X	X	X	X	✓	X	X
115-1190	Motorola MTP 850S, DMR	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1926	Motorola MTP 850	✓	✓	✓	✓	✓	✓	X	✓	✓
116-1934	Motorola MTH 800 MTH 650	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1218	EADS THR 800i	✓	✓	✓	✓	✓	✓	X	✓	✓
115-0028	EADS THR 9	?	?	✓	✓	✓	✓	X	✓	✓
115-1189	EADS TPH 700	✓	?	✓	✓	✓	✓	X	✓	✓
115-1254	RUAG COVERT 700	?	?	✓	✓	✓	✓	X	✓	✓
115-0063	EADS THR8, TH1n	?	?	✓	✓	✓	✓	X	✓	✓
115-1118	Matra SG 2	✓	✓	✓	✓	✓	✓	X	✓	X
115-0935	Sepura STP 8000	✓	✓	✓	✓	✓	✓	✓	✓	✓
115-1141	Sepura SRP/SRH/SRC series SRP2000, SRC3000, SRC3300, SRH3500, SRH3800, SRH3900	✓	✓	✓	✓	✓	✓	X	✓	✓
<b>MOTOROLA</b>										
115-1102	Motorola GP 300 GP68, GP88, GP300, GP308, GP2000, GP3188, PRO3150, P040, P080, CT250, CT450, GTX, SP50, P110, P1225, LTS2000, CP150, CP200	✓	✓	X	X	X	X	X	X	X
115-1121	Motorola GP 340 GP240, GP280, GP330, GP340, GP360, GP380, GP640, GP680, GP1280, GP140, GP320, GP328, GP338, GP329, GP339, HT750, HT1250LS, HT1550XLS, MTX850LS, MTX8250LS, MTX900, MTX950, MTX960, MTX9250, PTX700, PTX760, PTX780, PRO5150, PRO5350, PRO5450, PRO5550, PRO5750, PRO150, PRO7350, PRO7450, PRO7550, PRO7750, PRO9150, ATC-3500	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1122	Motorola GP 344 EX500, EX600, GP328plus, GP338plus, PRO5150elite, GP344, GP388, GL2000	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1132	Motorola GP 900 GP900, HT1000, MTX1000, XTS3000/Astro, XTS2250, XTS2500, XTS3500, XTS5000, MT2000, MTS2000, MTS2010, MTX8000, MTX838, MTX9000, JT1000	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1190	Motorola MTP 850S, DMR DP 3400/3401, DP 3600/3601, DP4400, DP4401, DP4600, DP4601, DP4800, DP4801, APX3000, APX6000, APX7000, XPR6550, P8260, P8268, P8200, P8208	✓	✓	✓	✓	✓	✓	X	✓	✓
<b>ICOM</b>										
115-1124	Icom IC-F3 / 90° (2.5/3.5) IC-02E, M12, IC-F3, IC-F34, IC-F3s, IC-F4, IC-F4s, IC-F25SR, IC-F34GS, IC-F2, IC-H6, IC H12, IC-J12, IC-M5, IC-U12, IC-U16, IC-A2, IC-A20, IC-A21, IC-A22f, IC-F3022, IC-F4022, IC-F4029	✓	✓	X	X	X	X	X	X	X
115-1127	Icom IC-F31 / 9 pin IC-F31GS, IC-F40, IC-F41GT, IC-F40GS, IC-F51, IC-F61, IC-F3062, IC-F3161, IC-F4062, IC-F4161, IC-F50, IC-F60	✓	?	✓	✓	✓	✓	X	✓	✓
<b>KENWOOD</b>										
115-1916	Kenwood TK 208 (2.5/3.5) TH-22, TH-25, TK-220, TK-320, TK-240, TK-340, TK-240D, TK-340D, TK-208, TK-308, TK-430, TK-431, TK-250, TK-350, TK-353, TK-260, TK-270, TK-260G, TK-360G, TK-360, TK-370, TK-270G, TK-370G, TK-248, TK-348, TK-2107, TK-3107, TK-2100, TK-3100 Pro-Talk, TK-3101 Free Talk XL, TK-2102, TK-3102 Pro-Power, TK-2160, TK-3160, TK-2170, TK-3170, TK-2360, TK-3201, TK-2302, TK-3302, TK-2300, TK-3300, TK-3301, TK-2306, TK-3306, TK-3360E, TK-3400	✓	✓	X	X	X	X	X	X	X
115-1916	NX-220, NX-320, TK-2000, TK-3000	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1123	Kenwood TK 280 (Multi-pin) TK-380, TK-390, TK-480, TK-481, TK-2140, TK-3140, TK-2180, TK-3180, NEXEDGE NX-200, NX-210, NX-300 <b>Exceptions: TK-280/290-11B needs modifications (Vin Direct connection)</b>	✓	✓	✓	✓	✓	✓	X	✓	✓
<b>YAESU VERTEX</b>										
115-1184	Yaesu Vertex VX-800 VX-600, VX-800, VX-900, MH-360, MH-450	?	?	X	X	X	X	X	X	X
115-1185	Yaesu Vertex VX-820 VX-P820 VX-700, VX-821, VX-824, VX-829, VX-920, VX-921, VX-581	✓	?	X	X	X	X	X	X	X
<b>Hytera</b>										
115-1249	X1e	?	?	✓	✓	✓	✓	X	✓	✓
115-1122	TC-780U	✓	✓	✓	✓	✓	✓	X	✓	✓
<b>VARIOUS</b>										
115-1108	Hirose HRS 6 pin Astro Digital Saber, Expo, MX1000, Tait TP9100 Side connector to HRS => Adapter without electronic, pinning must be checked	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1109	Hirose HRS 12 pin Astro Digital Saber, MX100, MX 3010 Side connector to HRS => Adapter without electronic, pinning must be checked	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1192	Harris RF-5800 / Thales MBITR	X	X	✓	✓	✓	✓	X	✓	✓
115-0018	Harris RF-7800	?	?	✓	✓	✓	✓	X	✓	✓
115-1182	Bosch FUG 10 FUG 11B	✓	✓	✓	✓	✓	✓	X	✓	✓
115-1250	Entel HT 2.0 Spiralkabel HT723	?	?	✓	✓	✓	✓	X	✓	✓